



OS and 3rd Party Patch List

Ultrasound

	FMI Name	Marketing Name	Security Patch Applicable Version	Microsoft OS Security patch identification information
UL	FMI-OSUL-JAN2019_A	TUS-A300, TUS-A500	V6.00*R000 - V7.00*R027	TUS AplioV7 V6.00R000 - V7.00R027\TUS
UL	FMI-OSUL-JAN2019_i	TUS-AI600, TUS-AI700, TUS-AI800, TUS-AI900	V2.0SP1000 - V2.0SP1014 V1.1SP0007 - V1.8SP1104	TUS i V2.0SP1000 V2.0SP1014 V1.1SP0007
UL	FMI-OSUL-MAR2019	TUS-AI600, TUS-AI700, TUS-AI800, TUS-AI900	V2.5SP000 - V4.0SP001	TUS AI Win10 x64 Security Patches to apply
UL	FMI-OSUL-APR2019	TUS-A300, TUS-A500	V6.00R000 - V7.00R027	TUS Aplio V7 V60R000 - V7.0R027 Security
UL	FMI-OSUL-JUNE2019	TUS-A300, TUS-A400, TUS-A500	TUS Aplio V6.00*R000 - V7.00*R029	FMI OSUL-JUN2019 Security Patch List.pdf
UL	FMI-OSUL-AUG2019_i	TUS-AI900/800/700/600	AI Series V2.0SP1000-V2.0SP1014, V1.1SP0007-V1.8SP1104	FMI OSUL-AUG2019_i Security Patch List.pdf
UL	FMI-OSUL-AUG2019_G	CUS-X200G V2.0SP0002	CUS-X200G V2.0SP0002	FMI OSUL-AUG2019_G Security Patch List.pdf
UL	FMI-OSUL-SEPT2019_A	TUS Aplio V6.00*R000 - V7.00*R029	TUS Aplio V6.00*R000 - V7.00*R029	FMI OSUL-SEPT2019_A Security Patch List.pdf
UL	FMI-OSUL-OCT2019_i	TUS-AI900/TUS-AI800/ TUS-AI700/TUS-AI600	AI Series V2.0SP1000 – V2.0SP1017 V1.1SP0007 – V1.8SP1104	FMI OSUL-OCT2019_i Security Patch List.pdf
UL	FMI-OSUL-JULY2020_A	TUS-A300, TUS-A500	TUS-A300, TUS-A500	FMI OSUL-JUL2020_A Security Patch List.pdf

CANON MEDICAL SYSTEMS USA, INC.

2441 Michelle Drive, Tustin CA 92780 | 800.421.1968

Canon Medical Systems USA, INC. 2023. All rights reserved. Design and specifications are subject to change without notice.

Made For life



	FMI Name	Marketing Name	Security Patch Applicable Version	Microsoft OS Security patch identification information
UL	FMI-OSUL-SEPT2020_i	"Aplio i series TUS-AI900, TUS-AI800, TUS-AI700, TUS-AI600 V2.5SP0000* - V2.5SP0006* V3.0SP0000* - V3.0SP0009* V3.1SP0000* - V3.1SP0005* V4.0SP0000* - V4.0SP0008"	TUS-AI900, TUS-AI800, TUS-AI700, TUS-AI600	FMI_OSUL-SEPT2020_i Security Patch List.pdf
UL	FMI-OSUL-NOV2020_iA_CUS	TUS-AI900/TUS-AI800/ TUS-AI700/TUS-AI600 CUS-AA550/ CUS-AA450 TUS-AI: V4.0SP1008*, SP1009*, SP1010* CUS-AA: V2.0SP1008*, SP1009*, SP1010*	TUS-AI900/TUS-AI800/ TUS-AI700/TUS-AI600 CUS-AA550/CUS-AA450	FMI_OSUL-NOV2020_iA_CUS Security Patch List.pdf
UL	FMI-OSUL-DEC2020_CUS	V2.0SP0002* - V2.0SP0007*	CUS-X100G/X200G	FMI_OSUL-DEC2020_CUS Security Patch List.pdf
UL	FMI-OSUL-JAN2021_i	"Aplio i series TUS-AI900, TUS-AI800, TUS-AI700, TUS-AI600 V2.5SP0000* - V2.5SP0007* V3.0SP0000* - V3.0SP0010* V3.1SP0000* - V3.1SP0008* V4.0SP0000* - V4.0SP0010*"	TUS-AI900, TUS-AI800, TUS-AI700, TUS-AI600	FMI_OSUL-JAN2021_i Security Patch List.pdf
UL	FMI_OSUL_MAR2021_A	Microsoft Windows 10 Enterprise 2016 LTSC operating system	Aplio Aseries - V7.10*R000-V7.10*R001	FMI_OSUL_MAR2021_A.pdf
UL	FMI-OSUL-MAY2021_CUS	Win 7 (x86) -	V4.0000*-V4.0SP0127*	FMI-OSUL-MAY2021_CUS.pdf

CANON MEDICAL SYSTEMS USA, INC.

2441 Michelle Drive, Tustin CA 92780 | 800.421.1968



	FMI Name	Marketing Name	Security Patch Applicable Version	Microsoft OS Security patch identification information
UL	FMI-OSUL-JULY2021_CUS	Microsoft Windows 10 Enterprise 2016 LTSB operating system	V2.0SP0002*- V2.0SP0008*	FMI-OSUL-JULY2021_CUS.pdf
	FMI-OSUL-JULY2021_Ai	Microsoft Windows 10 Enterprise 2016 LTSB operating system	"V4.6SP0008 V5.0SP0008* - V5.0SP0009* V5.1SP0008* - V5.1SP0009* V6.0SP0000* - V6.0SP0002**"	FMI-OSUL-JULY2021_Ai.pdf
	FMI-OSUL_JULY2021_Ai_v2-4	Microsoft Windows 10 Enterprise 2016 LTSB operating system	"Aplio i series TUS-AI900, TUS-AI800, TUS-AI700, TUS-AI600 V2.5SP0000* - V2.5SP0007* V3.0SP0000* - V3.0SP0010* V3.1SP0000* - V3.1SP0008* V4.0SP0000* - V4.0SP0010**"	FMI-OSUL_JULY2021_Ai_v2-4.pdf
	FMI-OSUL-AUG2021_Ai_CUS	Microsoft Windows 10 Enterprise 2016 LTSB operating system	TUS-AI900/TUS-AI800/TUS-AI700/TUS-AI600 CUS-AA550/CUS-AA450 TUS-AI: V4.0SP1008*, SP1009*, SP1010* CUS-AA: V2.0SP1008*, SP1009*, SP1010*	FMI-OSUL-AUG2021_Ai_CUS.pdf
	FMI-OSUL-SEPT2021_Ai	Microsoft Windows 10 Enterprise 2019 LTSC operating system	Aplio i-Series TUS-Ai700, TUS-Ai800, Tus-Ai900	FMI-OSUL-SEPT2021_Ai.pdf
	FMI-OSUL-OCT2021_A	Microsoft Windows 10 Enterprise 2016 LTSB operating system	Aplio Aseries - V7.10*R000-V7.10*R001	FMI-OSUL-OCT2021_A.pdf
	FMI-OSUL-JAN2022_Ai_CUS	Microsoft Windows 10 Enterprise 2019 LTSC operating system	TUS-AI900/TUS-AI800/TUS-AI700/TUS-AI600: V3.0SP1011*, V3.1SP1009*, V4.0SP1011*-V4.0SP1012* CUS-AA550/CUS-AA450 TUS-AI: V2.0SP1011*-V2.0SP1012*	FMI-OSUL-JAN2022_Ai_CUS.pdf
	FMI-OSUL-FEB2022_Ai-CUS ver 1-4	Windows 10 Enterprise 2016 LTSB	"TUS-AI900/800/700/600 V2.5SP0000* - V2.5SP0008* V3.0SP0000* - V3.0SP0012* V3.1SP0000* - V3.1SP0010* V4.0SP0000* - V4.0SP0012* CUS-AA550/450 V1.3SP0001* - V1.3SP0011* V2.0SP0000* - V2.0SP0012**"	FMI-OSUL-FEB2022_Ai-CUS ver 1-4.pdf
	FMI-OSUL-MAR2022_Ai_CUS ver 3-6	Microsoft Windows 10 Enterprise 2019 LTSC operating system	"TUS-AI900/800/700/600 V5.0SP0008* - V5.0SP1013* V5.1SP0008* - V5.1SP1013* V6.0SP0000* - V6.0SP1007* V6.5SP0000* - V6.5SP1007* CUS-AA550/450 V3.0SP0008* - V3.0SP0013* V4.0SP0000* - V4.0SP0007* V4.5SP0000* - V4.5SP0007**"	FMI-OSUL-MAR2022_Ai_CUS ver 3-6.pdf

CANON MEDICAL SYSTEMS USA, INC.

2441 Michelle Drive, Tustin CA 92780 | 800.421.1968



	FMI Name	Marketing Name	Security Patch Applicable Version	Microsoft OS Security patch identification information
UL	FMI-OSUL-APR2022_A	Microsoft Windows 10 Enterprise 2016 LTSC operating system	TUS-A500/A400/A300 V7.10*R000-V7.10*R001	FMI-OSUL-APR2022_A.pdf
	FMI-OSUL-MAY2022_Ai_CUS ver 3-6	Microsoft Windows 10 Enterprise 2019 LTSC operating system	"US-AI900/800/700/600 V5.0SP0008* - V5.0SP1013* V5.1SP0008* - V5.1SP1013* V6.0SP0000* - V6.0SP1007* V6.5SP0000* - V6.5SP1007* CUS-AA550/450 V3.0SP0008* - V3.0SP0013* V4.0SP0000* - V4.0SP0007* V4.5SP0000* - V4.5SP0007**	FMI-OSUL-MAY2022_Ai_CUS.pdf
	FMI-OSUL-MAY2022_A	Windows 7 Professional Service Pack 1 (x86) operating system.	TUS Aplio 300/500 V6.00*R000 - V7.00*R030	FMI-OSUL-MAY2022_A.pdf
	FMI-OSUL-MAY2022_A	Microsoft Windows 7 Professional SP 1	TUS Aplio V6.00*R00 - V7.00*R030	FMI-OSUL-MAY2022_A (Patches).pdf
	FMI-OSUL_MAR2021_i	Microsoft Windows 10 Enterprise 2016 LTSC operating system	"Aplio i series TUS-AI900, TUS-AI800, TUS-AI700, TUS-AI600 V2.5SP0000* - V2.5SP0007* V3.0SP0000* - V3.0SP0010* V3.1SP0000* - V3.1SP0008* V4.0SP0000* - V4.0SP0010**	FMI-OSUL_MAR2021_i.pdf
	FMI-OSUL-JULY2022_Ai_CUS ver 1-4	Microsoft Windows 10 Enterprise LTSC 2019 (x64)	"Windows 10 Enterp LTSC 2019 (x64) TUS-AI900/800/700/600 V3.0SP1011*-V3.0SP1012* V3.1SP1009*-V3.1SP1012* V4.0SP1008*-V4.0SP1012* V2.5SP1008*-2.5SP1009* CUS-AA550/450 V1.3SP1011*-V1.3SP1012* V2.0SP1008*-V2.0SP1012* CUS-AA000 V1.0SP1008* -V1.0SP1012**	FMI-OSUL-JULY2022_Ai_CUS ver 1-4.pdf

CANON MEDICAL SYSTEMS USA, INC.

2441 Michelle Drive, Tustin CA 92780 | 800.421.1968

Canon Medical Systems USA, INC. 2023. All rights reserved. Design and specifications are subject to change without notice.

Made For life



	FMI Name	Marketing Name	Security Patch Applicable Version	Microsoft OS Security patch identification information
UL	FMI-OSUL-JULY2022_Ai_CUS ver 1-4 - LTSB	Microsoft Windows 10 Enterprise LTSB 2016 (x64)	"Windows 10 Enterp LTSB 2016 (x64) TUS-AI900/800/700/600 V3.0SP1011*-V3.0SP1012* V3.1SP1009*-V3.1SP1012* V4.0SP1008*-V4.0SP1012* V2.5SP1008*-2.5SP1009* CUS-AA550/450 V1.3SP1011*-V1.3SP1012* V2.0SP1008*-V2.0SP1012* CUS-AA000 V1.0SP1008* -V1.0SP1012**"	FMI-OSUL-JULY2022_Ai_CUS ver 1-4 - LTSB.pdf
	FMI-OSUL-NOV2022_Ai_CUS ver 3-7	Microsoft Windows 10 Enterprise LTSC 2019 (x64)	"Windows 10 Enterprise LTSC 2019 (x64) TUS-AI900/800/700 V5.0SP0008* - V5.0SP1018* V5.1SP0008* - V5.1SP1018* V6.0SP0000* - V6.0SP1014* V6.5SP0000* - V6.5SP1014* V7.0SP0000* - V7.0SP0005* CUS-AA550/450/000 V3.0SP0008* - V3.0SP0018* V4.0SP0000* - V4.0SP0014* V4.5SP0000* - V4.5SP0014* V5.0SP0000* - V5.0SP0005**"	FMI-OSUL-NOV2022_Ai_CUS ver 3-7.pdf
	FMI-OSUL-SEPT2022_A	Microsoft Windows 10 Enterprise LTSB 2016 (x86)	Windows 10 Enterprise 2016 LTSB TUS-A500/A300 V7.10*R000-V7.10*R001	FMI-OSUL-SEPT2022_A.pdf
	FMI-OSUL-MAR2023_CUS Xario ver 2-2.2	Microsoft Windows 10 LTSB 2016 (x86)	"CUS-X100G/X200G V2.0SP0002* - V2.0SP0009* CUS-X100G V2.2SP0000* - V2.2SP0002**"	FMI-OSUL-MAR2023_CUS Xario ver 2-2.2.pdf
	FMIS-OSUL-APR2023_Ai_CUS ver 1-4	Microsoft Windows 10 LTSB 2016 (x86)	"TUS-AI V2.5SP0000* - V2.5SP0010* V3.0SP0000* - V3.0SP0015* V3.1SP0000* - V3.1SP0017* V4.0SP0000* - V4.0SP0016* CUS-AA550/450 V1.3SP0001* - V1.3SP0013* V2.0SP0000* - V2.0SP0014**"	FMIS-OSUL-APR2023_Ai_CUS ver 1-4.pdf
	FMI-OSUL-APR2023_Ai_CUS ver 1-4 LTSC 2019	Microsoft Windows 10 LTSC 2019 (x86)	"Windows 10 LTSC 2019 (x64) TUS-AI900/800/700/600 V3.0SP1011* - V3.0SP1015* V3.1SP1009* - V3.1SP1017* V4.0SP1008* - V4.0SP1016* V2.5SP1008* - V2.5SP1010* CUS-AA550/450 V1.3SP1011* - V1.3SP1013* V2.0SP1008* - V2.0SP1014* CUS-AA000 V1.0SP1008* - V1.0SP1014**"	FMI-OSUL-APR2023_Ai_CUS ver 1-4 LTSC 2019.pdf

CANON MEDICAL SYSTEMS USA, INC.

2441 Michelle Drive, Tustin CA 92780 | 800.421.1968



	FMI Name	Marketing Name	Security Patch Applicable Version	Microsoft OS Security patch identification information
UL	FMI-OSUL-APR2023_Ai ver 4.6-7 CUS ver 3-5	Microsoft Windows 10 LTSC 2019 (x86)	"Windows 10 2019 LTSC x64 TUS-AI900/800/700/600 V4.6SP0008* - V4.6SP1019 V5.0SP0008* - V5.0SP1019* V5.1SP0008* - V5.1SP1019* V6.0SP0000* - V6.0SP1014* V6.5SP0000* - V6.5SP1015* V7.0SP0000* - V7.0SP0005* CUS-AA550/450 V3.0SP0008* - V3.0SP0019* V4.0SP0000* - V4.0SP0014* V4.5SP0000* - V4.5SP0015* V5.0SP0000* - V5.0SP0005**	FMI-OSUL-APR2023_Ai ver 4.6-7 CUS ver 3-5.pdf
	FMI-OSUL-JUN2023_Ai ver 4.6-7 CUS ver 3-5	Windows 10 LTSC 2019 (x64) TUS-AI900/800/700 V4.6SP0008* - V4.6SP1019* V5.0SP0008* - V5.0SP1019* V5.1SP0008* - V5.1SP1019* V6.0SP0000* - V6.0SP1014* V6.5SP0000* - V6.5SP1015* V7.0SP0000* - V7.0SP0005* CUS-AA550/450/000 V3.0SP0008* - V3.0SP0019* V4.0SP0000* - V4.0SP0014* V4.5SP0000* - V4.5SP0015* V5.0SP0000* - V5.0SP0005*	TUS-i900, TUS-i800, TUS-i700, CUS-AA450, CUS-AA500	FMI-OSUL-JUN2023_Ai ver 4.6-7 CUS ver 3-5
	FMI-OSUL-JUN2023_Ai_CUS ver 1-4	TUS-AI V2.5SP0000* - V2.5SP0010* V3.0SP0000* - V3.0SP0015* V3.1SP0000* - V3.1SP0017* V4.0SP0000* - V4.0SP0016* CUS-AA550/450 V1.3SP0001* - V1.3SP0013* V2.0SP0000* - V2.0SP0014*	TUS-i900, TUS-i800, TUS-i700, CUS-AA450, CUS-AA500	FMI-OSUL-JUN2023_Ai_CUS ver 1-4
	FMI-OSUL-JULY2023_Ai_CUS ver 1-4 LTSC	Microsoft Windows 10 LTSC x64	"TUS-Ai900/800/700/600 V3.0SP1011* - V3.0SP1015* V3.1SP1009* - V3.1SP1018* V4.0SP1008* - V4.0SP1018* V2.5SP1008* - V2.5SP1010* CUS-AA450/550 V1.3SP1011* - V1.3SP1013* V2.0SP1008* - V2.0SP1014**	FMI-OSUL-JULY2023_Ai_CUS ver 1-4 LTSC
	FMI-OSUL-JULY2023_CUS X100G-X200G	Microsoft Windows 10 LTSB 2016 x86	"CUS-X100G/X200G V2.0SP0002* - V2.0SP0009* V2.2SP0000* - V2.2SP0002**	FMI-OSUL-JULY2023_CUS X100G-X200G

CANON MEDICAL SYSTEMS USA, INC.

2441 Michelle Drive, Tustin CA 92780 | 800.421.1968



	FMI Name	Marketing Name	Security Patch Applicable Version	Microsoft OS Security patch identification information
UL	FMI-OSUL-AUG2023_Ai ver 4.6-7 CUS ver 3-5	Microsoft Windows 10 LTSC x64	"TUS-AI900/800/700 V4.6SP0008* - V4.6SP1019* V5.0SP0008* - V5.0SP1019* V5.1SP0008* - V5.1SP1019* V6.0SP0000* - V6.0SP1014* V6.5SP0000* - V6.5SP1015* V7.0SP0000* - V7.0SP0005* CUS-AA550/450/000 V3.0SP0008* - V3.0SP0019* V4.0SP0000* - V4.0SP0014* V4.5SP0000* - V4.5SP0015* V5.0SP0000* - V5.0SP0005**"	FMI-OSUL-AUG2023_Ai ver 4.6-7 CUS ver 3-5
	FMI-OSUL-OCT2023_Ai CUS ver 1-4 LTSC	Microsoft Windows 10 LTSC x64	TUS-AI V2.5SP0000* - V2.5SP0010* V3.0SP0000* - V3.0SP0015* V3.1SP0000* - V3.1SP0017* V4.0SP0000* - V4.0SP0016* CUS-AA550/450 V1.3SP0001* - V1.3SP0013* V2.0SP0000* - V2.0SP0014*	FMI-OSUL-OCT2023_Ai CUS ver 1-4 LTSC
	FMI-OSUL-OCT2023_Ai CUS ver 1-4 LTSC	Microsoft Windows 10 LTSC x64	TUS-AI900/800/700/600 V3.0SP1011* - V3.0SP1015* V3.1SP1009* - V3.1SP1018* V4.0SP1008* - V4.0SP1018* V2.5SP1008* - V2.5SP1010* CUS-AA550/450 V1.3SP1011* - V1.3SP1013* V2.0SP1008* - V2.0SP1014*	FMI-OSUL-OCT2023_Ai CUS ver 1-4 LTSC
	FMI-OSUL-OCT2023_Ai ver 4.6-8 CUS ver 3-6 LTSC	Microsoft Windows 10 LTSC x64	TUS-AI900/800/700 V4.6SP0008* - V4.6SP1019* V5.0SP0008* - V5.0SP1019* V5.1SP0008* - V5.1SP1019* V6.0SP0000* - V6.0SP1016* V6.5SP0000* - V6.5SP1016* V7.0SP0000* - V7.0SP0008* V8.0SP0000* - V8.0SP0002* V8.1SP0000* - V8.1SP0002* CUS-AA550/450/000 V3.0SP0008* - V3.0SP0019* V4.0SP0000* - V4.0SP0016* V4.5SP0000* - V4.5SP0016* V5.0SP0000* - V5.0SP0008* V6.0SP0000* - V6.0SP0002*	FMI-OSUL-OCT2023_Ai ver 4.6-8 CUS ver 3-6 LTSC

CANON MEDICAL SYSTEMS USA, INC.

2441 Michelle Drive, Tustin CA 92780 | 800.421.1968



	FMI Name	Marketing Name	Security Patch Applicable Version	Microsoft OS Security patch identification information
UL	FMI-OSUL_MAR2021_i	Microsoft Windows 10 Enterprise 2016 LTSC operating system	"Aplio i series TUS-AI900, TUS-AI800, TUS-AI700, TUS-AI600 V2.5SP0000* - V2.5SP0007* V3.0SP0000* - V3.0SP0010* V3.1SP0000* - V3.1SP0008* V4.0SP0000* - V4.0SP0010**"	FMI-OSUL_MAR2021_i
	FMI-OSUL-DEC2023_Ai CUS ver 1-4 LTSC	Microsoft Windows 10 LTSC x64	"Aplio i series TUS-AI900, TUS-AI800, TUS-AI700, TUS-AI600 V2.5SP0000* - V2.5SP0007* V3.0SP0000* - V3.0SP0010* V3.1SP0000* - V3.1SP0008* V4.0SP0000* - V4.0SP0010**"	FMI-OSUL-DEC2023_Ai CUS ver 1-4 LTSC
	FMI-OSUL-DEC2023_Ai v4.6-8 CUS v 3-6	Microsoft Windows 10 LTSC x64	TUS-AI900/800/700 V4.6SP0008* - V4.6SP1019* V5.0SP0008* - V5.0SP1018* V5.1SP0008* - V5.1SP1019* V6.0SP0000* - V6.0SP1016* V6.5SP0000* - V6.5SP1016* V7.0SP0000* - V7.0SP0008* V8.0SP0000* - V8.0SP0002* V8.1SP0000* - V8.1SP0002* V8.2SP0000* CUS-AA550/450/000 V3.0SP0008* - V3.0SP0021* V4.0SP0000* - V4.0SP0016* V4.5SP0000* - V4.5SP0016* V5.0SP0000* - V5.0SP0008* V6.0SP0000* - V6.0SP0004* V6.2SP0000*	FMI-OSUL-DEC2023_Ai v4.6-8 CUS v 3-6
	FMI-OSUL-JAN2024_Ai-CUS v1-4 LTSC	Microsoft Windows 10 LTSC x64	TUS-AI900/800/700/600 V3.0SP1011* - V3.0SP1015* V3.1SP1009* - V3.1SP1018* V4.0SP1008* - V4.0SP1018* V2.5SP1008* - V2.5SP1010* CUS-AA550/450 V1.3SP1011* - V1.3SP1013* V2.0SP1008* - V2.0SP1014*	FMI-OSUL-JAN2024_Ai-CUS v1-4 LTSC
	FMI-OSUL-JAN2023_Ai CUS v1-4 LTSC	Microsoft Windows 10 LTSC x64	"TUS-AI900/800/700/600 V3.0SP1011* - V3.0SP1015* V3.1SP1009* - V3.1SP1018* V4.0SP1008* - V4.0SP1018* V2.5SP1008* - V2.5SP1010* CUS-AA550/450 V1.3SP1011* - V1.3SP1013* V2.0SP1008* - V2.0SP1014**"	FMI-OSUL-JAN2023_Ai CUS v1-4 LTSC

CANON MEDICAL SYSTEMS USA, INC.

2441 Michelle Drive, Tustin CA 92780 | 800.421.1968



	FMI Name	Marketing Name	Security Patch Applicable Version	Microsoft OS Security patch identification information
UL	FMI-OSUL-APR2024_Ai 4.6-7 CUS v3-6	Microsoft Windows 10 LTSC x64	"TUS-AI900/800/700 V4.6SP0008* - V4.6SP1019* V5.0SP0008* - V5.0SP1018* V5.1SP0008* - V5.1SP1019* V6.0SP0000* - V6.0SP1016* V6.5SP0000* - V6.5SP1016* V7.0SP0000* - V7.0SP0009* V8.0SP0000* - V8.0SP0002* V8.1SP0000* - V8.1SP0002* V8.2SP0000* - V8.2SP0001* CUS-AA550/450/000 V3.0SP0008* - V3.0SP0021* V4.0SP0000* - V4.0SP0016* V4.5SP0000* - V4.5SP0016* V5.0SP0000* - V5.0SP0009* V6.0SP0000* - V6.0SP0004* V6.2SP0000* - V6.2SP0001**"	FMI-OSUL-APR2024_Ai 4.6-7 CUS v3-6
	FMI-OSUL-MAY2024_AI CUS v1-4 LTSC	Microsoft Windows 10 LTSC	"TUS-AI V2.5SP0000* - V2.5SP0010* V3.0SP0000* - V3.0SP0019* V3.1SP0000* - V3.1SP0019* V4.0SP0000* - V4.0SP0019* CUS-AA550/450 V1.3SP0001* - V1.3SP0013* V2.0SP0000* - V2.0SP0019**"	FMI-OSUL-MAY2024_AI CUS v1-4 LTSC
	FMI-OSUL-APR2024_A v7 LTSC	Microsoft Windows 10 LTSC	"TUS-A500/A400/A300 V7.10*R000 - V7.10*R001 "	FMI-OSUL-APR2024_A v7 LTSC
	FMI-OSUL-JUNE2024_AI CUS v1-4 LTSC	Microsoft Windows 10 LTSC	"TUS-AI900/800/700/600 V3.0SP1011* - V3.0SP1019* V3.1SP1009* - V3.1SP1019* V4.0SP1008* - V4.0SP1019* V2.5SP1008* - V2.5SP1010**"	FMI-OSUL-JUNE2024_AI CUS v1-4 LTSC

CANON MEDICAL SYSTEMS USA, INC.

2441 Michelle Drive, Tustin CA 92780 | 800.421.1968

Canon Medical Systems USA, INC. 2023. All rights reserved. Design and specifications are subject to change without notice.

Made For life