



Canon Medical Systems USA, Inc.

OS and 3rd Party Patch List

	FMI Name	Marketing Name	Security Patch Applicable Version	Microsoft OS Security patch identification information
CT	FMI-OSCT-OCT2018	TSX Series	CT WinXP 64bit	MS17-010
MR	FMI-OSMR-JAN2019	MRT-1504/A4, MEXL-1504/A4, MRT-1504/S4, MEXL-1504/S4, MRT-1504/S3, MEXL-1504/S3, MRT-3010/S5	"V2.31R009, R010, R011,R108: Titan V2.50R007: Titan 3T"	MRI V2.31 V2.5 security patches list
MR	FMI-OSMR-FEB2019	MEXL-1504/U2, MEXL-1510/S2, MEXL-1510/S3	"V3.0SP0047, V3.11SP0047: Vantage Elan V3.1SP0030: Vantage Titan"	MRI MPower V3.0SP0047 V3.1SP0047
UL	FMI-OSUL-JAN2019_A	TUS-A300, TUS-A500	V6.00*R000 - V7.00*R027	TUS AplioV7 V6.00R000 - V7.00R027\TUS
UL	FMI-OSUL-JAN2019_i	TUS-AI600, TUS-AI700, TUS-AI800, TUS-AI900	"V2.0SP1000 - V2.0SP1014 V1.1SP0007 - V1.8SP1104"	TUS i V2.0SP1000 V2.0SP1014 V1.1SP0007
CT	FMI-OSCT-FEB2019	TSX-305A	V8.3x	CT Win7 V8 patch list
MR	FMI-OSMR-MAR2019	MRT-1550/S1, MRT-1550/S2, MRT-1550/S3, MRT-1550/S4, MEXL-1550/S1, MEXL-1550/S2, MEXL-1550/S3, MEXL-1550/S4	"V5.0SP1020: Galan 3T V4.5SP1020: Orian"	MRI V4.55 V5 Security Patch List
MR	FMI-OSMR-MAR2019A	MRT-2020, MRT-1504, MRT-1510, MRT-2004, MRT-3010	V4.0SP0010 V4.0SP1050	MPower V4.05SP0010 - V4.0SP1050
UL	FMI-OSUL-MAR2019	TUS-AI600, TUS-AI700, TUS-AI800, TUS-AI900	V2.5SP000 - V4.0SP001	TUS AI Win10 x64 Security Patches to apply
UL	FMI-OSUL-APR2019	TUS-A300, TUS-A500	V6.00R000 - V7.00R027	TUS Aplio V7 V60R000 - V7.0R027 Security

CANON MEDICAL SYSTEMS USA, INC.

2441 Michelle Drive, Tustin CA 92780 | 800.421.1968